Missouri Department of Transportation



Ed Hassinger, District Engineer

St. Louis Metro District
2309 Barrett Station Road
Ballwin, Mo. 63021
(314) 301-1439
Fax (314) 301-1437
or (573) 526-0016
www.modot.mo.gov
Toll Free 1-888 ASK MoDOT

QUOTATION TABULATION

General Services

Results Posted: 10:05 am, 7/8/11

Thank you for your response to our Request for Quotation **SL12-005-R7**, **Anti-Icing Skid Frame**. For your information, the following is a tabulation of all responses which were received.

If you have any questions, please contact me at the address/phone number shown above.

Buyer: Stephanie Austin Rashid, General Services Technician

Quantity	U/M	DESCRIPTION	Monroe Truck Equipment
		(including size and/or part #'s)	TOTAL UNIT COST
1	Ea	Anti-Icing/De-Icing Skid Frame	\$3,447.62
		Requirements:	
		*Tank skid must have provisions for self loading and	
		unloading	
		*The tank skid must be manufactured from mild steel with	
		longitudinals manufactured of 3/16" thick material	
		*Must have steel wheels on the front edge of the skid for	
		ease of loading and unloading	
		*Skid must be designed for mounting of the pump valves	
		and spray bars	
		*Storage legs must be provided with the front storage leg	
		assembly being self-actuating	
		*Skid assembly must be held in place by a tailgate latch	
		assembly and ratchet nylon straps	
		*Skid assembly must be painted with a high quality,	
		industrial powder coat paint	
		*Rear storage leg assembly must have provisions for a	
		travel position	
		*Must include one set of (4) tank hoops for 1635 gallon	
		tank	
		*Must be comparable/similar or functionally equivalent to	
		Monroe Truck Equipment Skid Part #00012276	